





Existing condition of the superstructure (girders)

Ranges from poor to fair



Corrosion of steel girders (from surface rust to holes) is a common problem with the Claude Allouez Bridge superstructure.



More examples of steel deterioration shown above include cracks in steel connection plates and pack rust between steel plates and girders.